

Video to USB adapter, Model VA11A

INSTALLATION AND OPERATING INSTRUCTIONS

IMPORTANT: Use of the VA11A Video to USB adapter requires Windows[®] 95 OSR 2.1 with USB support, Windows 98, Windows Me, Windows 2000, or Windows XP.

Note: You might need to have your Windows CD handy, in case Windows needs to install additional components.

DO NOT plug the VA11A USB adapter into your PC until you install the X10 software.

1. Download the desired X10 software from:

www.x10.com/software

2. Run the installation program. Select the directory where the software will be installed, and follow the on screen instructions.

3. When the installation program instructs you to plug in the USB adapter, plug the VA11A into your USB port. Your computer will recognize that new hardware has been connected and will complete the installation.

4. Plug an XCam camera or Video Receiver (both sold separately) into the VA11A as per their instructions.

® Windows is a Registered Trademark of Microsoft Corporation.

F.C.C. CAUTION - THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION.

NOTE: NO CHANGES OR MODIFICATIONS MAY BE MADE TO THE UNITS. ANY CHANGES MADE TO THE UNITS WILL VOID THE USER'S AUTHORITY TO OPERATE THE EQUIPMENT.

X10 Wireless Technology, Inc. LIMITED 1-YEAR WARRANTY

X10.com, a division of X10 Wireless Technology, Inc. (X10) warrants X10 products to be free from defective material and workmanship for a period of one (1) year from the original date of purchase at retail. X10 agrees to repair or replace, at it's sole discretion, a defective X10 product if returned to X10 within the warranty period and with proof of purchase.

If service is required under this warranty:

1. Call 1-800-675-3044 or visit www.x10.com, or e-mail sales@x10.com to obtain a Return Merchandise Authorization (RMA) number.
2. Return the defective unit postage prepaid to X10 (see address on back).
3. Enclose a check for \$4.00 to cover postage and handling.
4. Enclose a dated proof of purchase.
5. X10 is not responsible for shipping damage. Units to be returned should be packed carefully.

Please visit www.x10.com/warranty

to complete your on-line warranty registration. Thank you.

For help or more information on setup, please visit: www.x10.com/support

VA11A-10/01